

ALT-8015 Radio Altimeter Test Set, Software Version 1.4.5 Release

This information bulletin is to inform current users of the ALT-8015 that a new version of operational software is now available. The new software can be obtained by contacting the VIAVI Service Department in Wichita, Kansas.

Summary of changes:

All ALT-8015 users testing APN-209J/K/L radio altimeters will require this operational software update. Implementation of the software will change the currently installed version to 1.4.5. Recalibration is not required.

Summary of changes:

1. Added test capability for APN-209J/K/L radio altimeter variants
2. Improved Self-Test

Downloading and Installing New Software:

Installation of the new software is outlined in the operator's manual 92956 (section 5.2.2). The latest version of the ALT-8015 software is export controlled and can be obtained by contacting VIAVI Solutions and requesting software part number 92879.



Revision	Date	Reason	Reference
AA	11/30/2016	Release of v1.4.0 software	500000007734
AB	6/8/2017	Release of v1.4.1 software	500000007954
AC	10/12/2018	Release of v1.4.5 software	500000008652



Contact Us +1 316 522 4981
AvComm.TechSales@viavisolutions.com

To reach the VIAVI office nearest you, visit
[viavisolutions.com/contact](https://www.viavisolutions.com/contact).

© 2020 VIAVI Solutions Inc.
Product specifications and descriptions in this document are subject to change without notice.
alt8015-srn-avi-nse-ae
30191100 900 0720 [viavisolutions.com](https://www.viavisolutions.com)